

## ABSTRACT

Two inverters (INV1, INV2) supply phase currents to three-phase coils (Y1, Y2). Although two phase currents must  
5 conventionally be measured and four current sensors are thus required, according to the present invention, the number of phase currents to be measured is reduced as a result of use of an observer for phase current estimation.